






# News from KFI56

# KFI5606


## What we have found

- Confirmation of a short-circuit



## What was done

- Finger back to its original position



## What follows?

- Do not remove KFI56 from the machine.
- We would like to perform HV tests the sooner as possible.

