

Pbar Complex Summary (week #44) 1/3

- AD
 - Horn in fault.
 - Local Reset. Impossible to do Reset remotely.
 - Water leak on the C10 cryo-pump.
 - Fixed Friday.
 - Water leak on E Cooler.
 - Changed a water pipe.
 - PSB + 2 turns
 - 6% more protons on target, we get +5% at the exit of AD
 - 1800e10 from PS, 1600e10 on target, 3.7e7 out AD

Pbar Complex Summary (week #44) 2/3

- ELENA
 - Several correctors OFF in Alpha line.
 - First line has exchanged the control board.
 - Control board of the filament of the source has been repaired.
 - Tests ongoing
 - Glitch on a "Gbar" vacuum pump triggered the closure of the fast vacuum valve on LNE50
 - Piquet VAC opened it
- New AD + ELENA vistar deployed.
 - [AD / ELENA vistar details : - PS Operations - Controls Wikis \(cern.ch\)](#)

Pbar Complex Summary (week #44) 3/3

