

## Linac 4

<b>Machine Coordinator last week</b>	Skowronski Piotr		
<b>Machine Coordinator this week</b>	Sanchez Alvarez Jose-Luis		
<b>Statistics</b>			
<b>Availability</b>	98%		
<b>Facility Status</b>			
<b>Summary</b>	OK		
<b>Issues</b>	1. On Wednesday PS access to Switchyard blocked the beam delivery towards PSB for 2h30 2. On Friday power supply of corrector L4L.RCH.121 tripped 3 times in a row, rebooting FGC gateway fixed it - 30 minutes 3. On Thursday Chopper tripped – 4 min		
<b>Plans</b>	Regular operation. During accesses to Switchyard dedicated measurements investigating variations along the pulse.		
<b>Intervention Request</b>			
No	<b>Duration</b>		<b>Preferred date/time</b>
<b>Reason</b>			
<b>Impact</b>			