

ISIEC Form & Safety Clearance process



Every set-up must undergo this safety process, before operations. This includes:

- Main users set-ups
- Set-ups taking parasitic beam
- Set-ups coming back with the same installation as the previous month/year/etc.

The EP Safety Office should be contacted (and the ISIEC process started) from few weeks/months to 1 week before your experiment is installed at CERN, depending on the hazards and risk implications.

ISIEC Form & Safety Clearance process



1. Go on the website: <https://ep-th-safety.web.cern.ch/isiec-safety-clearance> (you must Sign In to access the ISIEC form)
2. Submit the **ISIEC** (*Initial Safety Information for Experiments at CERN*) **form** with the details related to your experiment (description, hazards, etc) **at least 1 week** before the operation
3. You will receive a confirmation email and you will be contacted by the EP Safety Office to organise the **inspection visit on site** (once the installation of the set-up is **completed!**)
4. After the inspection, the **remarks** (if any) will be communicated to you. If no major remarks are present, you will receive the **Safety Clearance** form via email. If present, minor remarks will be listed in this form. Make sure they are all resolved before taking beam!
5. The Safety Clearance is valid for an operation time of 3 weeks. Please, contact the EP Safety Office if your beam time is extended.