DRD1-WG6 Proposal

- G. Charles (IJCLab), Wires
- A. Delbart (Irfu Saclay), TPC
- R. De Oliveira (Cern), MPGD
- G. laselli (INFN), RPC/MRPC
- F. Jeanneau (Irfu Saclay), MPGD
- I. Laktineh (IP2I), RPC/MRPC

Mandate and objectives

Mandate

- Production aspects of gaseous detectors covering all essential construction elements
- Development of production techniques and innovative solutions
- Transfer to industry

Objectives

- 1: Development and maintenance of common production facilities and equipment
- 2: Quality control and large volume productions
- 3: Collaboration with industrial partners
- 4: Establishment and support of a forum for sharing experi- ences, knowledge, and best practices

Production facilities and equipment

Reference	Description	Deliverable Nature	
Task 6.1.1	Production Needs: detector type	Report with estimation	
	and size, production volumes and quality	for each technology	
Task 6.1.2	_	Report with inventory for	
	type and size, production volumes and production quality	each technology	
Task 6.1.3	Needs and Capability Matching	Report with required re-	
	(costs)	sources in terms of equip-	
		ment and personnel	
Task 6.1.4	Identify Resource Pooling strate-	Resource Requests	
	gies for the creation or the upgrade		
	of production facilities		

QC and production

Reference	Description	Deliverable Nature
Task 6.2.1	QA/QC protocols for each tech-	Report
	nology	
Task 6.2.2	Inventory of missing but required	Report
	instrumentation for QA/QC	

Collaboration with industrial partners

Reference	Description	Deliverable Nature
Task 6.3.1	Technology transfer checklist	Report
Task 6.3.2	Technology transfer database	Database
	(project, industrial partner)	

Collaborative forum

Reference	Description	Deliverable Nature
Task 6.4.1	Establishment and support of a forum for	Online Forum
	sharing experiences, knowledge, and best	
	practices on gaseous detectors	