


X-Box Summary



27.11.2024



X-Box 2 TD31 N3 N4: Structure B


- **Restarted after visit 18.10.2024**
- 100:1 ratio, all power to Structure B
- Pulse width 100ns
- **Changed pulse shape (Igor's request)**
- **Fixed problem with pulse counter**
 - Saved old and corrected TDMS files
 - Corrected PXI Pulse count.txt too
- **Running flat 50MW**
 - BDR 1e-5
- **Stopped – SU6 broken**

X-Box 3: HEK Measurements




X-Box 3: HEK Measurements



Freq. shift 0MHz



Freq. shift -20MHz



X-Box 3: HEK Measurements





home.cern

X-Box 2: Reminder on BD classification

