

I have corrected the paper following the suggestions. About the first comment on page 2: the positioning of the acoustic beacons on the seabed is performed by the ROV equipped with an acoustic pinger. The position of the ROV is determined by means of a USBL (Ultra Short BaseLine) system with an accuracy better than 0.2 m with respect to the DGPS position of the ship.