

PS							
<b>Machine Coordinator last week</b>		PSR & TT2 (Gianfranco EN-ACE), SWY (Marcel, Oliver BE-OP)					
<b>Machine Coordinator this week</b>		PSR & TT2 (Gianfranco EN-ACE), SWY (Marcel, Oliver BE-OP)					
Beam Scheduled							
<b>East Area</b>	Yes/No	<b>nTOF</b>	Yes/No	<b>AD</b>	Yes/No	<b>SPS</b>	Yes/No
Beam Availability by Destination (AFT)							
<b>AD</b>	%	<b>EA N</b>	%	<b>EA T8</b>	%	<b>EA T9</b>	%
<b>nTOF</b>	%	<b>SPS</b>	%				
Facility Status							
<b>Summary</b>	PSR & TT2: YETS SWY: hardware commissioning has started 12/02.						
<b>This week</b>	Monday: IST for PS main units (under responsibility of EN-ACE) Tuesday: DSO test for SWY, PSR and TT2 (under responsibility of EN-ACE) Since Wednesday: HWC for SWY. Short accesses for KFA28 and F16.BTV135 were required. Thursday: scheduled accesses for heat run, polarity check of three aux. magnets (exchanged during YETS) and audio/visual patrol of all aux.magnets. Acc-testing tested on testable test equipment with HWC-test cycle Friday: Completion of HWC checklist for SWY						
<b>Next week</b>	Monday 17/02: - MTG intervention from 9:00 to 12:00 - Pulsing SMH26 - Access for SY-BI, intervention on PU37 amplifier. - Non conformity of fire wall below PS-East area will be fixed. Re-patrol of PS sector 5 will be required - Re-patrol TT2 sector 5, lost after HSE-RP intervention  <b>Saturday 22/02:</b> (in practice Monday 24/02) PSR and TT2 handover from EN-ACE to OP.						
Intervention Request							
Yes / No	<b>Duration</b>		<b>Preferred date/time</b>				
<b>Reason</b>							
<b>Impact</b>							