


Alarm statistics w04-05 2025

G. Rigoletti



EP-DT
Detector Technologies

Alarms w04-05



Michal (23/01-30/01)

- LHCb UT side C inlet pressure alarm
 - Due ongoing tests, alarm temporarily blocked by Michal
- LHCb stop of the system for AUG
 - Systems stopped by Michal before the start of AUG
- RICH2 H chamber pressure, several times
 - No actions taken, system in backup. Alarm blocked
- TRD Mixer injection too long
 - No actions taken