



Contribution ID: 19

Type: not specified

RF concerns for the restart of the PS and SPS

Wednesday, 18 January 2006 10:35 (10 minutes)

This presentation will outline changes, which may disrupt the restart of the PS and SPS RF systems. Many of these changes are occurring outside the RF group. They include; responsibility for the various B-train systems, SPS timing software, remote computer access to hardware, moving to the CCC.

Presenter: HOFLE, Wolfgang

Session Classification: Session 1: What Has Been Done