



=



Introduction to general meeting 20-21 November 2012 at CERN

- ☐ Review the activity of each group
- ☐ Assess the readiness for the year to come
- ☐ Re-Organize the task where needed
- ☐ Consider AID-box activities

Goals

- × Prototype 2: reaching 0.35 % X_0 with
 - × new flex cable: narrower and aluminum traces → fabricated, not test yet
 - × lighter SiC foam at 4% density
- × Test beam with power-pulsing
- × Produce at least a few ladders, + about 10 for the AID box