

LHC Machine Protection has worked extremely well in these first years of LHC operation, but in a few isolated cases issues presented themselves. Failures like design faults, software bugs or manual mistakes pointed out weaknesses in the protection mechanisms. This paper recalls a number of these issues, as experienced by operations, highlighting which follow-up actions were devised and identifying which actions might still be missing (e.g. new interlocks or new procedures).