

MTTR and spare parts policy for BT equipment

The mean-time-to-repair (MTTR) and the spare parts policy for non-LHC related equipment under the responsibility of AB-BT is reviewed. Items with particularly long repair time will be identified and strategies to mitigate their effect will be discussed. The organization of interventions (via expert lists or piquet service) for septa and kickers will be presented.