

## LTC Extended meeting



Contribution ID: 35

Type: **not specified**

## Magnets & QPS towards operation

*Monday 3 March 2008 15:10 (35 minutes)*

- o How to operate up to 8 sectors together
- o Recovery after a quench: how much time does it take? Is expert intervention required? How can this be improved?
- o Equipment folder: tests results, handling of non-conformities, performance below specs, machine as commissioned vs. machine as nominal
- o Alarms/signals/SW available in CCC
- o Piquet/Experts availability

**Presenter:** CATALAN LASHERAS, Nuria

**Session Classification:** Session 2 - Preparation for Circulating Beam - Part I