


# **IRWG – Proposal of Strategy Version 0.0**

V. Kain, B. Mikulec

# New Phase



- ❑ Machine preparation tests coordinated by OP
  - Coordination with equipment experts and MEF
  - Equipment experts should participate
- ❑ Hardware test and accesses: coordinated by MEF
- ❑ Before “cold check-out”, collaboration for planning between MEF, equipment experts and OP (machine responsible) required.