

Change Notes (4-21-2016):

1. Changed HADD connections.
2. Pullups/pulldowns on NB flow, etc., ClkA, ClkB
3. Added reset on PORIN.
4. Changes JTAG pin order.
5. SAMPA 3 and 4 part values.
6. Changed SDA_0 to SDA.

