


Flow Meter Calibration



- | | | | |
|---|---|---|--|
| ● Room (22°C) | ● Cold (-40°C) | ● Hot (40°C) | ● Cool (0°C) |
| ● Kinda Cold (-20°C) | ⋯ Linear (Room (22°C)) | ⋯ Linear (Cold (-40°C)) | ⋯ Linear (Hot (40°C)) |
| ⋯ Linear (Cool (0°C)) | ⋯ Linear (Cool (0°C)) | ⋯ Linear (Kinda Cold (-20°C)) | |