LEIR FOM Report Week 49/50



Machine Operation

Tuesday 5th

Extraction kicker KFH32 tripped several times with open circuit fault

Friday 6th

RF source in LINAC3 & RF cavities in LEIR tripped, restarted ok

Saturday 8th


- E-cooler problem several trips of ER.ECTSOL, PIPO called and local reset performed
- E-cooler ER.ECTSOL problem returned, PIPO called

Sunday 9th

- E-cooler ER.ECTSOL power supply, PIPO & major events piquet resolve the problem, DCCT chassis was replaced no further problems since
- RF source in LINAC3 & RF cavities in LEIR tripped, restarted ok



Root Cause Fault Time Distribution





MD's & other activities

12/12/2017

Wednesday 6th

 EARLY beam delivered to CHARM for users from the European Space Agency.

Monday 11th

EPC measurements on ETL.BHN10 from 15:00hrs – 17:00hrs.

Transverse instability studies on MDNOM – Nicolo Biancacci Detailed chromaticity measurements and tune scans on MDOPTIC – Angela Hernandez

