



Preliminary Observations from the V3 test

Torsten, Tobias, Rama, Pierre, Mathieu, Maria, Antoine, Alick
3 October 2013

Crab cavity test: Preliminary results




Crab cavity test: Preliminary results




Crab cavity test: Preliminary results


Residual Resistance



Attempt at RRR







Magnetization







$\sim 10\mu\text{T}$
 $\Rightarrow O(10-20 \text{ n}\Omega)$




Cavity Shape issues



Calibration: P_T response to square pulse



Temperature monitors



Leak tests:

