

# Status of procedures and documents for DQW crab cavity

Procedure	Status
<i>Visual inspection</i>	<b>Completed</b>
<i>Dimensional and thickness control of subassemblies</i>	<b>Under preparation</b>
<i>Trim tuning (frequency measurement, trim tuning steps)</i>	<b>Under preparation</b>
<i>Buffered Chemical Polishing at JLab</i>	<b>Obsolete – to be updated</b> with Jlab changes
<i>High Pressure Rinsing at JLab</i>	<b>Obsolete – to be updated</b> with Jlab changes
<i>Tuning strategy (tuning ranges, sensitivity, target frequencies)</i>	<b>Under preparation</b>

  

Appendices	Status
<i>Cavity description</i>	<b>Completed</b>
<i>Subassembly description</i>	<b>Completed</b>
<i>Frequency shifts and uncertainties</i>	<b>Under revision</b>