
## **SPS W28-29**





## **SPS W28-29**



## → HiRadMad TCDIL:

- → Finished this morning at about 1:30 AM
- → All requested shots delivered thanks for the dedicated time
- → In the end it was well handled between production and HI shots

## → RF intervention this morning:

- → Last week there was a replacement of an RF module
- → It was then observed an offset between the RF phase and the reading of the phase pickup
- → Today, 3h with low intensity SFTPRO beam or nothing to redo the 200 MHz cavity phasing and to re-adjust the 1-turn delay feedback for the 200 MHz cavity line 4
  - All changes will then be verified with beam